

## [Kimo LX 100 Lux Light Exposure Intensity Meter Photometer](#)

### Lux Light Level Chart

100000	Extreme Australian Summer Sunshine
50000	British Summer Sunshine
5000	Overcast Sky
500	Well-lit Office
300	Minimum for Easy Reading
50	Typical Passageway
15	Good Main Road Lighting
10	Sunset
5	Typical Side Road Lighting
2	Minimum Security Risk Lighting ('EXIT' signs)
1	Twilight
0.30	Clear Full Moon
0.10	Typical Moonlight
0.001	Typical Starlight
0.0001	Poor Starlight